


Q H=35400 / 3,

Q H



	-1,5 /		-2 /		-4 /		-5 /					
		1.57 ^{+0.16} _{-0.08}		2.23 ^{+0.28} _{-0.12}		4.65 ^{+0.47} _{-0.43}		5.82 ^{+0.58} _{-0.29}				
	4	5										
	900	1200										
	16x10 ⁶											
	1,25±0,25	1,6±0,32	2±0,4									
	3800±760	5000±100	3600±720	3800±760								
	25000±5000											
	1,6	1,6	2,2	2,5	2,3							
	0,1-0,15		0,1-0,2									
Q ^c n=40,38 / (9650 /), /	160		210	420	520							
/ (8500 / ³), ³ / Q ^c n=35,4	180		235	470	590							
	70			120								
	65 391		65 391	72 795	72 795							
	D1	D2	D3	D4	L	L1	L2	L3	L4	L5	h2	
-1,5 /	244	108	276	141	951	264	240	309	500	37	180	250
-2 /	267	108	276	141	951	264	240	312	500	36	180	250
-4 /	374	159	375	205	1188	375	318	428	600	52	235	360
-5 /	374	159	375	205	1188	375	318	428	600	52	235	360